Contents

Preface *xix*
Acknowledgments *xxii*

PART 1 Background Matters *1*

Chapter 1 Manufacturing Management *3*
1.1 Mechanical Production *3*
1.2 Industrial and Production Engineering *12*
1.3 Industrial Engineering: Production Planning and Control *14*
1.4 Group Technology *20*
1.5 Process Planning: Computer-Aided Process Planning *24*
1.6 Manufacturing Resources Planning *33*
1.7 Production Scheduling, Monitoring, and Control *37*
1.8 Just in Time *38*
1.9 Conclusion *41*
References *42*
Questions *43*

Chapter 2 Engineering Materials and Their Properties *45*
2.1 Introduction *45*
2.2 Mechanical Properties *46*
2.2.1 The Tensile Test *46*
2.2.2 Hardness Testing *50*
Table 2.1 Comparison of Hardness Numbers *51*
2.2.3 Notched Bar Impact Tests *51*
2.2.4 High Temperature Tests *52*
2.2.5 Fatigue Testing *52*
2.3 Structures and Transformations in Metals and Alloys *53*
2.3.1 Crystal Structures *53*
Table 2.2 Interatomic Distances of Selected Crystals *54*
2.3.2 Crystal Imperfections: Dislocations *54*
2.3.3 Grain Boundaries and Deformation *56*
2.4 Alloys: Phase Diagrams *56*
2.4.1 General *56*
2.4.2 The Fe-C Phase Diagram *60*

2.5 Heat Treatment of Metals *63*
2.5.1 Allotropic Metals: Steels *63*
2.5.2 Phase Diagram for Al Alloys: Precipitation Hardening *67*
2.5.3 Solid Solution Treatment *69*
2.5.4 Summarizing Methods of Strengthening Metals *70*
2.6 Engineering Metals *71*
2.6.1 Steels *71*
Table 2.3 Specifications of Selected SAE-AISI Low-Alloy Steels *73*
Table 2.4 Properties of the 4340 Steel *74*
Table 2.5 Stainless Steels *75*
Table 2.6 Tool Steels *76*
2.6.2 Cast Irons *76*
2.6.3 Aluminum Alloys and Magnesium Alloys *78*
Table 2.7 Aluminum Casting Alloys *78*
Table 2.8 Wrought Aluminum Alloys *80*
2.6.4 Copper, Nickel, Zinc, and Their Alloys *80*
Table 2.9 Selected Copper and Nickel Alloys *81*
Table 2.10 Zinc Die-Casting Alloys *81*
2.6.5 Titanium Alloys *82*
Table 2.11 Titanium Alloys *82*
2.6.6 Superalloys *83*
Table 2.12 Superalloys *84*
Table 2.13 Refractory Metals *85*
2.6.7 Refractory Metals *84*
2.7 Plastics *85*
2.7.1 Polymerization Methods, Bonding, and Structures *86*
2.7.2 Additives *88*
2.7.3 Thermoplastics *89*
2.7.4 Thermosets *90*
2.7.5 Elastomers *92*
2.7.6 Special Applications of Polymers *92*
Table 2.14 Room-Temperature, Short-Time Parameters of Selected Plastics *96*
2.8 Ceramics *96*
Table 2.15 Hardness of Some Ceramics *97*
2.9 Composite Materials *99*
Table 2.16 Mechanical Properties of GRP and CRP in Comparison with Metals *101*
References *102*
Questions *103*

Chapter 3 Primary Metalworking *105*
3.1 Introduction: Iron and Steel Industries *105*
3.2 Blast Furnace Operations *111*
3.2.1 Design of the Furnace: Inputs and Outputs *111*
3.2.2 Chemistry of the Blast Furnace Reactions
Table 3.1 Pig Iron Compositions *116*
Table 3.2 Utilities Requirements of a Self-Contained Blast Furnace Plant with Two Furnaces Producing 8400 Tons of Iron Per Day *118*

3.3 Steel-Making Furnace Operations *119*
3.3.1 The Open-Hearth (OH) Process *119*
3.3.2 Basic Oxygen Furnace (BOF) *122*
3.3.3 Electric Furnaces *124*
3.3.4 Summary of Steel Production *126*
3.4 Ingots: Continuous Casting of Slabs *127*
3.5 Hot Forming: Open-Die Forging and Rolling *130*
3.5.1 Primary Hot Rolling *131*
3.5.2 Rolling Mill Configurations *134*
Example 3.1 Specific Power in Rough Hot Rolling *138*
3.5.3 Hot Forming of Tubes and Pipes *139*
3.6 Cold Rolling of Sheet Metal *142*
3.7 Casting *142*
3.7.1 Expendable Mold Processes *146*
3.7.2 Permanent-Mold Casting *152*
3.7.3 Casting Materials *156*
3.8 Aluminum: Manufacture, Use, and Processing *157*
3.8.1 Manufacture and Use *157*
3.8.2 Processing *160*
3.9 Other Metals *164*
3.10 Powder Metallurgy *165*
3.10.1 The Powder *166*
3.10.2 Compacting *167*
3.10.3 Sintering *168*
References *171*
Questions *172*

PART 2 Traditional Processes *175*

Chapter 4 Metal Forming Technology *177*
4.1 General Operating Conditions, Machines, and Tools *177*
4.1.1 Hot Forming *178*
4.1.2 Cold Work and Anneal Cycle *181*
Example 4.1 Combining Cold Work and Annealing for Desired Material Properties *184*
4.2 Basic Machines for Metal Forming *185*
Table 4.1 Ratings of Forging Hammers *190*
Table 4.2 Parameters of Presses *193*
Example 4.2 Kinematics of a Crank Mechanism *194*
Example 4.3 The Crank and Toggle Mechanism *196*
Example 4.4 Work Done in a Forging Hammer *197*
Example 4.5 Energy of a Hammer Strike Lost in the Motion of the Anvil *198*
Example 4.6 Slowdown of the Flywheel in a Punching Operation *199*
4.3 Forging *201*
4.3.1 Open-Die Forging (ODF) *201*

4.3.2 Roll Forging *204*
4.3.3 Closed-Die Forging (CDF) *205*
4.3.4 Hot and Cold Upsetting *209*
Table 4.3 Principal Parameters of Hot Upsetting Machines *211*
4.3.5 Extrusion *215*
4.3.6 Forgeability of Metals *217*
4.4 Sheet Metal Forming *218*
4.4.1 Basic Operations and Presses *218*
4.4.2 Automation of Presswork *223*
4.4.3 Press Brake Work *229*
4.4.4 Cold Roll Forming *230*
4.4.5 Formability of Sheet Metals *232*
4.5 Numerical Control (NC) in Metal Forming *236*
4.5.1 Numerically Controlled (NC) Bending on a Press Brake *236*
4.5.2 NC Turret Punch Presses *237*
References *240*
Questions *241*

Chapter 5 Metal Forming Mechanics *242*
5.1 Elementary Concepts *242*
5.1.1 The Stress-Strain Diagram *243*
5.1.2 Stress in Three Dimensions *246*
5.1.3 Yielding: Plastic Deformation *249*
5.1.4 Special Cases of Yielding *251*
5.2 Bulk Forming: Basic Approach—Forces, Pressures *253*
5.2.1 Wire Drawing: Work, Force, and Maximum Reduction Without Friction *253*
5.2.2 Wire Drawing: Pressure on the Die, and Axisymmetric Yielding *254*
5.2.3 Wire Drawing with Friction *255*
Example 5.1 Wire Drawing with Friction: Solution by Discrete Integration *255*
5.2.4 Extruding a Round Bar *258*
5.2.5 Rolling with Back and Forward Tension: Plane-Strain Yielding *258*
5.3 Bulk Forming: Effects of Redundant Work and of Friction *260*
5.3.1 Nonhomogeneous Deformation: Redundant Work *260*
5.3.2 The Effect of Friction in Plane Strain *266*
Example 5.2 Determine p_{max} and p_{av} for Plane-Strain Compression Under the Combined Conditions of Dry Friction and of Friction Shear Flow *270*
5.3.3 Effect of Friction in Upsetting a Cylindrical Workpiece *273*
Example 5.3 Using a Gravity Hammer for Cold Upsetting of a Cylindrical Workpiece *276*
5.3.4 Summary of the Effects of Friction and Redundant Work *280*
5.3.5 Force and Neutral Point in Cold Rolling *282*
Example 5.4 Compute the Pressures and Forces in Rolling *286*
5.3.6 Material Failure in Bulk Forming *288*

5.4 Analysis of Plate- and Sheet-Metal Forming *290*
5.4.1 Simplified Analysis *290*
5.4.2 Elastic and Plastic Bending *293*
Example 5.5 Determine the Shape of the Deformation of a Plate Loaded in the Middle Between Supports *297*
Table 5.1 The Coordinates of the Deflection Curve *298*
5.4.3 Residual Stresses *299*
5.4.4 Failures and Limitations in Bending *302*
Table 5.2 Smallest Radii in Bending (ρ_{min}/h) *303*
5.4.6 Drawing of a Non-Strain-Hardening Material *306*
5.4.7 Radial Drawing of a Strain-Hardening Material *308*
Example 5.6 Compute the Variation of the Radial Drawing Stress for a Strain-Hardening Material *311*
5.5 Chatter in Cold Rolling *312*
5.5.1 A Simple Rolling Chatter Theory *312*
References *317*
Questions *317*
Problems *318*

Chapter 6 Processing of Polymers *324*
6.1 Introduction: Properties Used in Processing *324*
6.2 Summary of Selected Polymers *325*
Table 6.1 U.S. Sales of Most Common Polymers *326*
6.2.1 Thermoplastics *330*
6.2.2 Thermosets *332*
6.2.3 Elastomers *332*
6.3 Thermal Properties: Viscosity *333*
Table 6.2 Processing Parameters of Thermoplastics *335*
Table 6.3 Thermal Properties of Polymers *336*
6.3.1 Newtonian Flow in a Rectangular Channel (Slit) *337*
6.3.2 Non-Newtonian, Power-Law Flow in a Flat Channel *340*
Example 6.1 Newtonian and Non-Newtonian Flow in a Flat Channel *341*
Example 6.2 Viscous Heat Generation *345*
Example 6.3 Is the Flow in Example 6.1 (b2) Laminar? *345*
6.3.3 Flow in a Tube *345*
6.4 Processing Methods and Operations *347*
6.4.1 General Considerations *347*
6.4.2 Casting *348*
6.4.3 Compression (CM) and Transfer Molding (TM) *349*
6.4.4 Extrusion *349*
6.4.5 Injection Molding (IM) *356*
6.4.6 Thermoforming *364*
6.5 Analysis of the Plasticating Screw *366*
6.6 Processing of Polymer-Based Composites *368*
6.6.1 Preforms *368*
6.6.2 Hand Lay-Up and Spray-Up Molding *370*
6.6.3 Filament Winding *370*

6.6.4 Pultrusion *374*
References *375*
Questions *375*
Problems *376*

Chapter 7 Cutting Technology *377*
7.1 Introduction *377*
7.2 Single-Point Tool Operations *378*
7.2.1 Metal Removal Rate: Cutting Force *379*
Example 7.1 Metal Removal Rate in Turning *379*
Table 7.1 Specific Force and Power for Selected Workpiece Materials *380*
7.2.2 The Tools *381*
7.2.3 The Machine Tools *386*
7.3 Drilling and Allied Operations *390*
7.3.1 Metal Removal Rate: Force, Torque, and Power *393*
7.3.2 Drilling Machines *394*
7.4 Multipoint Tool Operations: Milling *396*
7.4.1 Mean Chip Thickness, MRR, and Power *398*
Example 7.2 Mean Chip Thickness in Milling *401*
Example 7.3 Power in Face Milling *402*
7.4.2 Design of Milling Cutters *402*
7.4.3 Milling Machines *405*
7.5 Broaching *408*
References *412*
Questions *413*
Problems *413*

Chapter 8 Cutting Mechanics *415*
8.1 The Cutting Force *416*
8.1.1 Chip Generation *418*
Example 8.1 Shearing and Friction Power in Chip Formation *424*
Example 8.2 Strain and Strain Rate in Chip Formation *425*
8.1.2 Simplified Formulations *425*
8.2 Temperature Field in the Chip and in the Tool *427*
8.2.1 Shear Plane Temperature *427*
Table 8.1 Mechanical and Thermal Properties of Selected Workpiece Materials *428*
8.2.2 Computing the Temperature Field *431*
Example 8.3 Compute Temperature Fields for a Particular Case *436*
Example 8.4 Compute Temperature Fields for Four Different Materials *440*
8.3 Cutting-Tool Materials *443*
Table 8.2 Usage of Different Tool Materials (1997) *445*
Table 8.3 Hardness and Melting Temperature of Tool-Material Constituents *447*
8.3.1 High-Speed Steels *447*

Table 8.4 Compositions and Properties of Selected High-Speed Steels *449*
8.3.2 Sintered Carbides *450*
Table 8.5 Classification of Sintered Carbides *454*
8.3.3 Ceramic Tools *455*
8.3.4 Borazon and Polycrystalline Diamond *456*
8.4 Tool Wear: Choice of Cutting Conditions, Machinability of Materials *458*
8.4.1 Tool Wear *458*
8.4.2 Tool Wear Rate and Tool Life *462*
Example 8.5 Determine the Parameters of the Tool Life Equation *463*
8.4.3 Optimizing Cutting Speed and Feed in a Single Cut Operation: Taylor-Type Tool Life Equation *465*
8.4.4 Optimizing Cutting Speed and Feed in a Single Cut Operation: Tool Life Equation Non-Taylor-Type *468*
8.4.5 Optimizing Speeds and Feeds for a Multi-Tool Operation: Tool Life Equation of the Taylor Type *469*
Example 8.6 Optimize Speeds and Feeds for a Multitool Operation According To Figure 8.44 *471*
Example 8.7 How Does the Number of Tools Cutting Simultaneously Affect Optimum Speed and Optimum Tool Life? *473*
8.4.6 General Conclusions for the Choice of Cutting Speeds and Feeds *475*
Table 8.6 Parameters Used in Cutting Data Banks *476*
8.5 Tool Breakage: Wear and Breakage in Milling *477*
8.5.1 Breakage in Continuous Cutting *477*
8.5.2 Tool Wear and Breakage in Interrupted Cutting *481*
8.5.3 Flank Wear in Milling *483*
References *486*
Questions *486*
Problems *488*

PART 3 Machine Tools *493*

Chapter 9 Design of Machine Tools: Drives and Structures *495*
9.1 General Description of Machine-Tool Design *495*
9.2 Specifying the Characteristics of Main Drives *501*
Example 9.1 Drive Characteristics *504*
9.3 Accuracy of Machine Tools *506*
9.3.1 Geometric Accuracy: Machine Tool Metrology *507*
Example 9.2 Determining Errors at Offsets *513*
9.3.2 Weight Deformations *516*
9.3.3 Deformations Under Cutting Forces *519*
Example 9.3 Copying of Form Error of Workpiece *523*
9.4 Review of Fundamentals of Mechanical Vibrations *525*
9.4.1 Vibrations: Natural, Forced, Self-Excited *525*
9.4.2 Harmonic Variables *527*
9.4.3 Basics of Vibrations: Transfer Function of a System with a Single Degree of Freedom *529*

9.4.4 Transfer Functions of a Selected System with Two Degrees of Freedom: Uncoupled Modes in Two Directions *532*
Example 9.4 Forced Vibration of a System with Two Uncoupled Modes in a Plane *533*
Example 9.5 Determine the Transfer Function (*Y*/*F*) for a System with Two Uncoupled Modes in a Plane *534*
9.5 Forces and Forced Vibrations in Milling *537*
9.5.1 Accuracy of End Milling: Straight Teeth, Static Deflection *537*
9.5.2 The Dynamics: Forced Vibrations, Straight Teeth *538*
Example 9.6 Variation of *Fx* and *Fy* Forces on Cutters with Straight Teeth *539*
9.5.3 Forced Vibrations and Their Imprint as Error of Location of the Machined Surface *542*
Example 9.7 Slotting with a Two-Fluted Cutter: Resonant Vibration *542*
Example 9.8 Slotting with a Two-Fluted Cutter, Nonresonant Conditions *544*
Example 9.9 Up-Milling with a Four-Fluted Cutter with Straight Teeth: Only One Tooth in Cut; Forces and Deflections *545*
9.5.4 Forces on End Mills with Helical Teeth *548*
Example 9.10 Forces in Milling with Helical Teeth *551*
Example 9.11 Prove that the Cutting Force on a Four-Fluted Cutter in Slotting Is Constant *553*
Example 9.12 Show that at Certain Axial Depths of Cut the Milling Force Is Constant *555*
9.5.5 Errors of Surface Produced by End Mills with Helical Teeth: Static Deflections *556*
9.6 Chatter in Metal Cutting *559*
9.6.1 General Features *559*
9.6.2 Mechanisms of Self-Excitation in Metal Cutting *560*
9.6.3 The Condition for the Limit of Stability of Chatter *563*
9.6.4 Analyzing Stability of a Boring Bar *565*
9.6.5 Another Way of Deriving the Limit of Stability, Using the Nyquist Criterion *568*
9.6.6 Time Domain Simulation of Chatter in Turning *570*
Example 9.13 Simulation of Chatter in Turning *573*
9.6.7 Chatter in Milling *575*
9.7 Designing Machine-Tool Structures for High Stability *579*
9.8 Effect of Cutting Conditions on Stability *586*
9.9 Case Study: High-Speed Milling (HSM) Machine for Aluminum Aircraft Parts *594*
9.9.1 High Speed Milling in General: Operations with a Lack of Stiffness *594*
9.9.2 Developing HSM Machine for Aluminum Aircraft Parts *598*
References *604*
Questions *605*
Problems *606*

Chapter 10 Automation *611*

10.1 Automation of Machine Tools *613*
Table 10.1 Actions to Automate and Devices to Use *613*
10.1.1 Rigid and Flexible Automation *616*
10.2 Machine Tools with Rigid Automation *618*
10.2.1 Single-Spindle Automatic Lathes *618*
10.2.2 Multispindle Automatic Lathes *622*
10.2.3 Dial-Index Machines and Transfer Lines *625*
10.3 Numerically Controlled Machine Tools *628*
10.3.1 Basic Operation *628*
10.3.2 Adaptive Control *633*
10.3.3 Turning Centers *634*
10.3.4 Machining Centers *635*
10.4 Computerized, Flexible Manufacturing Systems *639*
10.5 Positional Servomechanism: Review *647*
10.5.1 Characteristics of the Servomotor *648*
10.5.2 Step Input Response of the Servomotor *650*
10.5.3 Time-Domain Simulation of the Servomotor *653*
10.5.4 The Positional Servomechanism *654*
10.5.5 Step Input Response of the Positional Servo *656*
10.5.6 Time-Domain Simulation of the Positional Servo *657*
Example 10.1 Performance of Positional Servos *658*
Table 10.2 Parameters of the Four Test Cases *659*
10.5.7 Response to a Ramp Input of the Positional Servo *659*
10.6 Errors of Two-Dimensional Tool Path *661*
Example 10.2 The Velocity Lag *661*
Example 10.3 Ramp Input Response: Overshoot on Stopping a Motion *662*
Example 10.4 Two-Coordinate Motions: Corner Motion *664*
Example 10.5 Effect of the Dead Zone *666*
Example 10.6 Distortions of a Continuous Path *667*
10.7 Adaptive Control for Constant Force in Milling *674*
10.7.1 Analysis of Stability *674*
Example 10.7 Limit of Stability of the Adaptive Control System *677*
Example 10.8 Simulation of a Stable and an Unstable A/C System *678*
10.7.2 Summary of Analyses of Numerical and Adaptive Control *681*
10.8 Positional Servo Driving a Spring-Mass System *681*
10.8.1 Two Basic Specifications: MT and ROB *681*
10.8.2 The Two Basic Alternatives, A and B *682*
10.8.3 The "Machine Tool" Case with SMD System in the Feedback Loop: MT/A *683*
Example 10.9 Limit of Stability: The "Machine Tool" Case: MT/A *685*
Example 10.10 Response To a Ramp Command of the Case MT/A (SMD System in the Loop) *687*
10.8.4 Flexibility Outside of the Loop: Case MT/B *687*
10.8.5 The "Robot" Case with SMD System within the Loop: ROB/A *689*
Example 10.11 Limit of Stability of the Robot Case: ROB/A *689*

10.8.6 Accelerometric Feedback Applied To the ROB/A System *691*
Example 10.12 Using Accelerometer Feedback *692*
Example 10.13 The "Robot Arm": Configuration B *693*
10.9 Feedforward Compensation *694*
10.9.1 Ideal Servodrive *694*
10.9.2 Real Servodrive *697*
Example 10.14 Feedforward Compensation in One Coordinate *700*
10.9.3 Numerical Derivation of the Feedforward Compensation *701*
Example 10.15 Using Numerical Derivation of the Feedforward Command: Motion in One Coordinate *703*
Example 10.16 Feedforward Compensation for Constant Jerk Motion *704*
10.10 Simplified Robot Kinematics and Dynamics *709*
10.10.1 Introduction: Types of Robots and Their Uses *709*
10.10.2 Simplified Kinematics *715*
10.10.3 Dynamics of the 2D Polar Case *717*
Example 10.17 Feedforward Compensation in Two Dimensions *718*
10.11 Conclusion *723*
References *724*
Questions *724*
Problems *725*

PART 4 Assembly and Nontraditional Processes *733*

Chapter 11 Assembly: Material Handling and Welding *735*
11.1 Introduction *735*
11.2 Material Handling *737*
11.3 Mechanical Joining *743*
11.4 Assembly *746*
11.5 Design for Assembly *756*
11.6 Welding Processes *757*
11.6.1 Introduction *757*
11.6.2 Oxyacetylene Welding *762*
11.6.3 Arc Welding Processes *764*
11.6.4 Other Welding Processes *775*
11.7 Control of the Arc *784*
11.7.1 Melting Rates *784*
Table 11.1 Melting Rate Coefficients *785*
11.7.2 Self Regulation of the Arc in SMAW and GMAW *787*
Example 11.1 SMAW, GMAW, SAW. Step Change Δh *791*
Example 11.2 Step Change Δf: GMAW, Const e *792*
11.7.3 Servo Control in SAW *793*
Example 11.3 Servo Control of SAW *795*
Example 11.4 Servo Control of SAW: Effect of a Change of the Gap Δh *799*
11.7.4 Time Domain Simulation *799*
Example 11.5 Servo Control of SAW *800*

11.8 Heat Transfer in Arc Welding *803*
11.8.1 Continuous Field Solution: Thick Plate Formulation *803*
Example 11.6 Temperature Profile Along the *Y*-Axis *805*
Example 11.7 Temperature Profiles for Three Different Materials *806*
Table 11.2 Thermal Parameters of Three Materials *806*
Example 11.8 Heat Input Versus Welding Speed for Three Materials *808*
11.8.2 Gradients: Cooling Rates *809*
11.8.3 The 2D Case: The "Thin Plate" Line Heat Source q'' *810*
Example 11.9 Temperature Profiles for the Thin Plate *811*
Example 11.10 Heat Energy per Unit Length Versus Welding Speed for the Thin Plate *812*
11.8.4 The Finite Difference Approach: Thin Plate (2D) *813*
Example 11.11 Using the Finite-Difference Method to Compute Temperature Fields *816*
11.9 Residual Stresses and Distortions *822*
References *828*
Questions *829*
Problems *830*

Chapter 12 Nontraditional Processes *833*
12.1 Introduction *833*
12.2 Ultrasonic Machining (USM) *836*
12.3 Water Jet Cutting (WJC) *838*
Table 12.1 Performance of WJC for Various Materials *839*
12.4 Electrochemical Machining (ECM) *839*
12.4.1 Metal Removal Rate: Working Gap *841*
Table 12.2 Specific Volume V_s for Selected Materials *842*
Example 12.1 Transient Gap in ECM *844*
Example 12.2 Electrolyte Flow *845*
12.5 Chemical Machining (CHM), Photochemical Machining (PCM) *853*
Table 12.3 Maskants and Etchants *854*
12.6 Electro-Discharge Machining (EDM) *859*
Table 12.4 Comparison of Dielectric Fluids for Brass Electrodes and Tool-Steel Workpieces *861*
Table 12.5 Comparison of Tool Materials *861*
12.7 Laser Beam Machining (LBM) *864*
Table 12.6 Operational Comparison of CO_2, Nd:YAG, and Excimer Lasers *868*
Example 12.3 Power in Laser Drilling *868*
Table 12.7 Physical and Thermal Properties of Selected Metals *869*
Table 12.8 High-Power Laser Cutting *875*
12.8 Electron Beam Machining (EBM) *875*
Table 12.9 Holes Drilled by EBM in Various Materials *877*
Table 12.10 Slot Cutting by EBM in Various Materials *877*
Example 12.4 Power in EBM Cutting *877*
12.9 Oxygen Cutting (OC) *879*
12.10 Plasma Arc Cutting (PAC) *881*

12.11 Electronics Manufacturing *882*
12.12 Additive CNC Manufacturing (Rapid Prototyping) *889*
12.12.1 Rapid Modeling *890*
12.12.2 Rapid Tooling *897*
12.13 Conclusion *903*
References *904*
Questions *905*
Problems *907*
Index *909*