

Contents

1	General Considerations	1
1.1	Introduction	1
1.1.1	Introduction	1
1.1.2	Meaning of the Word "Powder"	3
1.1.3	Sample and Specimen	3
1.1.4	Why Powder Diffraction?	4
1.1.5	Difficulties and Limitations of Powder Diffraction	5
1.1.6	Fundamentals of Diffraction	5
1.1.7	Analysis of Powder Diffraction Patterns	7
1.2	Powder Diffraction	9
1.2.1	History of Powder Diffraction	9
1.2.2	Programs for the Analysis of Powder Diffraction Data	11
1.2.3	Crystal Structures from Powder Diffraction Data	13
1.2.4	Pattern Decomposition for Accurate Intensities	15
1.2.5	Profile Shape Functions	22
1.2.6	Early <i>Ab Initio</i> Crystal Structure Determinations from Powder Diffraction Data by Pattern Decomposition	26
1.2.7	<i>Ab Initio</i> Structure Determination by Direct Methods in Powder Diffraction	31
1.2.8	Crystal Structures Determined by Direct Methods	34
1.2.9	Preferred Orientation in Powder Diffraction	36
1.2.10	Line Broadening: Crystallite Size, Strain and Stress	37
2	The Rietveld Method	41
2.1	The Rietveld Method	41
2.1.1	The Early Days of the Rietveld Method	41
2.1.2	The Method	44
2.1.3	Rietveld Refinement with X-Ray Powder Diffraction Data	48
2.1.4	Critical Assessment of the Rietveld Method	51
2.1.5	Guidelines for Rietveld Refinement	56
2.2	Special Applications of the Rietveld Method	64
2.2.1	Quantitative Phase Analysis by the Rietveld Method	64
2.2.2	Texture Analysis Using the Rietveld Method	70

3	The Two Stage Method	73
3.1	Introduction and Background	73
3.1.1	Concept of the Two Stage Method	73
3.1.2	The Two Stage Method in Comparison to Rietveld Refinement	76
3.2	Profile Analysis and Profile Fitting	77
3.2.1	Characteristics of Powder Diffraction Line Profiles	77
3.2.2	Outline of Profile Fitting	78
3.2.3	Profile Functions	79
3.2.4	The Instrument Function	82
3.2.5	Instrument Function with Seven Lorentzians	84
3.2.6	Determination of Integrated Intensities through Profile Fitting	87
3.2.7	Angle Dependence of the Profile Shapes	88
3.2.8	Resolution of Profile Fitting	90
3.2.9	High Resolution Powder Diffraction – Lattice Parameters	91
3.3	Examples of Profile Fitting in the Two Stage Method	95
3.3.1	Examples for PROFAN	95
3.3.2	Examples for HFIT	98
3.4	POWLS	99
3.4.1	Structure Refinement with POWLS	99
3.4.2	The Program POWLS	99
3.4.3	Preparation of a Model Structure	103
3.4.4	Observations	105
3.4.5	Refinement	106
3.4.6	Preferred Orientation	106
3.5	Specimen and Preferred Orientation	107
3.5.1	Specimen Preparation	107
3.5.2	Random Distribution	108
3.5.3	Calculational Corrections	109
3.5.4	Crystallite Size Effects	110
3.6	R-Values	112
3.6.1	General Remarks	112
3.6.2	R-Values in Powder Diffraction	113
3.6.3	Background	114
3.6.4	Dealing with Background	115
3.6.5	Background in Rietveld Programs	115
3.6.6	The Profile R-Value	119
3.6.7	The Weighted Profile R-Value	120
3.6.8	The Bragg R-Value	121
3.6.9	Conclusion	125
3.7	Structure Refinement by the Two Stage Method	125
3.7.1	Refinement with POWLS	125
3.7.2	Examples Using the Two Stage Method and the Program POWLS	128
3.7.3	Comparison of the Rietveld Method and the Two Stage Method	128

3.7.4	Merits and Limitations of the Rietveld Method and the Two Stage Method	134
3.7.5	Conclusion	136
3.8	Analysis of Quartz	136
3.8.1	Sample Preparation	137
3.8.2	Experiments	137
3.8.3	Sample Rotation during Experiments	138
3.8.4	Crystal Structure Refinement with POWLS of α -Quartz Collected with Cu K α Radiation	139
3.8.5	Refinement of α -Quartz Data Collected with Synchrotron X-Rays	141
3.9	Texture Analysis with the Two Stage Method Using Neutron Diffraction	147
3.9.1	Introduction	147
3.9.2	The Position Sensitive Detector JULIOS	149
3.9.3	Data Collection	149
3.9.4	Data Evaluation	151
3.9.5	Examples of Texture Analysis	152
3.10	Selected Examples for the Application of the Two Stage Method	160
3.10.1	Electron Density Distribution of an Olivine Sample by Fourier Methods	160
3.10.2	Electron Density Distribution in CeO ₂	164
3.10.3	Crystal Structure Analysis of Yb ₂ O ₃	167
3.10.4	Application in High Pressure Research	172
3.10.5	Cation Distribution in a Thin Film Garnet Sample	176
3.11	Structure Determination from Energy Dispersive Data	181
3.11.1	Structure Determination from Energy Dispersive Data	181
3.11.2	Synchrotron Radiation	182
3.11.3	Neutron Diffraction by Time-of-Flight Measurements	183
3.11.4	Simultaneous Angle and Position Resolving Neutron Diffraction by Time-of-Flight Measurements	184
3.11.5	Electronic Zooming	188
3.11.6	Analysis of TOF Data	190
3.11.7	Laue Diffraction with Neutrons by Time-of-Flight Measurements	193
3.12	Conclusion	194
	References	195
	Appendix – An Example of POWLS for Quartz	203
	Index	219