

## Contents

<b>1. Thermal and moisture issues of roofs.....</b>	<b>5</b>
1. 1 Thermal engineering assessment of a single-skin flat roof.....	16
1. 2 Thermal engineering assessment of a double-skin flat roof.....	28
1. 3 Flat roofs unventilated.....	35
1. 4 Thermal engineering assessment of pitched roofs.....	36
<b>2. Condensation of water vapour on the inner surface of building structures.....</b>	<b>43</b>
2. 1 Causes of surface condensation of water vapour.....	43
2. 1. 1 Filling of openings in exterior walls.....	46
2. 1. 2 Vertical and horizontal corners.....	47
2. 1. 3 Thermal Bridges.....	49
2. 1. 4 Lining, lintels, window sills and frames for window openings.....	51
2. 1. 5 Other possibilities of surface condensation.....	53
2. 2 Physical principle of state changes in the indoor air caused by a change in interior use.....	59
2. 3 Technical measures for problems with condensation on the interior surface of building structures.....	62
2. 3. 1 Change of use.....	62
2. 3. 2 Modification of perimeter structures.....	62
2. 4 Ensuring the required interior air parameters by natural ventilation or by ventilation.....	68
2. 5 Combination of the above options.....	69
<b>3. Designing floors for the remediation of damp masonry.....</b>	<b>70</b>
3. 1 Reasons for intervention in existing floors .....	70
3. 2 Additional insertion of thermal insulation in floors.....	71
3. 3 Floor air gaps.....	74
3. 3. 1 Air gap created by roofing.....	74
3. 3. 2 Air gap created by special plastic fittings.....	74
3. 3. 3 Air gap height design.....	76
3. 3. 4 Thermal engineering assessment of ventilated floor constructions gap.....	77
3. 4 Assessment of floor air cavities by CFD (computational fluid dynamics) .....	81
3. 5 Reconstruction of floor cavities.....	81
<b>4. Thermal engineering assessment of interior wall cavities situated above the floor applied as part of the remediation of damp masonry.....</b>	<b>82</b>
4. 1 Division of air cavities .....	82
4. 2 Air cavities located on the inside of a damp wall above floor level.....	82
4. 2. 1 Pre-set walls.....	82
4. 2. 2 Interior cladding.....	84
4. 3 Thermal engineering assessment of wall cavities located on the inside of the wall above floor level.....	84
4. 3. 1 Unventilated air cavities.....	84
4. 3. 2 Ventilated air cavities with supply and extraction of air to the interior.....	87
4. 3. 3 Ventilated air cavities with supply and extraction of air to the exterior.....	88
4. 3. 4 Ventilated air cavities with air intake from the interior and extraction to the exterior..	90
<b>5. Numerical solution of the function of wall air cavities located below the floor level applied in the remediation of damp masonry.....</b>	<b>91</b>