

CONTENTS*

PREFACE	vii
LIST OF REFERENCE TABLES	xiii

PART I. INDUSTRIAL STATISTICS

1. Use of Variables in Acceptance Inspection for Percent Defective	3
W. ALLEN WALLIS, <i>University of Chicago</i>	
2. Tolerance Limits for Normal Distributions	95
ALBERT H. BOWKER, <i>Stanford University</i>	
3. Multivariate Quality Control, Illustrated by the Air Testing of Sample Bombsights	111
HAROLD HOTELLING, <i>University of North Carolina</i>	
4. Effects of Rounding or Grouping Data	185
CHURCHILL EISENHART, <i>National Bureau of Standards</i>	
5. Acceptance Inspection When Lot Quality Is Measured by the Range	225
THE EDITORS, based on work by M. A. Girshick, <i>U. S. Bureau of the Census</i>	
6. Variability of Amount of Inspection for Double, Multiple, and Sequential Sampling	235
THE EDITORS, based on work by Myra Levine, <i>Socony-Vacuum Oil Company</i>	

PART II. PLANNING EXPERIMENTS

7. Planning and Analyzing Experiments for Comparing Two Percentages	247
EDWARD PAULSON, <i>University of North Carolina</i> W. ALLEN WALLIS, <i>University of Chicago</i>	
8. Planning and Interpreting Experiments for Comparing Two Standard Deviations	267
CHURCHILL EISENHART, <i>National Bureau of Standards</i>	
9. Utilization of Limited Experimental Facilities When the Cost of Each Measurement Depends on Its Magnitude	319
MILTON FRIEDMAN, <i>University of Chicago</i>	
10. Experiments in Which the Independent Variable Is Known Only in Terms of a Probability Distribution	329
THE EDITORS, based on work by J. Wolfowitz, <i>Columbia University</i>	
11. Planning an Experiment for Estimating the Mean and Standard Deviation of a Normal Distribution from Observations on the Cumulative Distribution	339
MILTON FRIEDMAN, <i>University of Chicago</i>	

* An analytical table of contents appears at the beginning of each chapter.

12. Abandoning an Experiment Prior to Completion.	353
THE EDITORS, based on work by	
L. J. Savage, <i>University of Chicago</i>	
Kenneth J. Arnold, <i>University of Wisconsin</i>	
M. A. Girshick, <i>U. S. Bureau of the Census</i>	
13. Planning Experiments Seeking Maxima.	363
MILTON FRIEDMAN, <i>University of Chicago</i>	
L. J. SAVAGE, <i>University of Chicago</i>	
PART III. TECHNIQUES AND TABLES	
14. Probability That Sample Means Are in Opposite Order to Population Means.	375
CHURCHILL EISENHART, <i>National Bureau of Standards</i>	
15. Significance of the Largest of a Set of Sample Estimates of Variance .	383
CHURCHILL EISENHART, <i>National Bureau of Standards</i>	
HERBERT SOLOMON, <i>Stanford University</i>	
16. Inverse Sine Transformation of Proportions.	395
CHURCHILL EISENHART, <i>National Bureau of Standards</i>	
17. Elements of Sequential Analysis.	417
W. ALLEN WALLIS, <i>University of Chicago</i>	
INDEX.	431