

---

# Contents

---

List of Figures .....	xiii
Preface .....	xvii
Acknowledgments .....	xxi

<b>Chapter 1</b> Failure and Success in Manufacturing—The General Motors–Toyota NUMMI Joint Venture.....	1
---	---

## SECTION I The Age of the Artisan

<b>Chapter 2</b> The Stone Age.....	9
2.1 The First Manufacturing Technique—Cutting .....	10
2.2 The Second Manufacturing Technique—Changing Material Properties.....	13
2.3 The Third Manufacturing Technique—Joining .....	14
2.4 The Fourth Manufacturing Technique—Coating .....	15
2.5 The Fifth Manufacturing Technique—Casting and Molding .....	17
2.6 The Sixth Manufacturing Technique—Forming .....	18
2.7 Manufacturing at the End of the Stone Age .....	19
Bibliography .....	20

<b>Chapter 3</b> The Urban Revolution—The Emergence of Society.....	23
3.1 The Neolithic Revolution—From Nomadic Hunters to Settled Farmers .....	24
3.2 Early Division of Labor—The Emergence of the Artisan during the Bronze Age .....	26
3.3 At the Bottom of the Social Hierarchy—Slave Labor and Its Supervision.....	28
3.4 Transition from the Bronze Age to the Iron Age .....	30
Bibliography .....	31

<b>Chapter 4</b>	Advances during Antiquity .....	33
4.1	Breaking the Energy Constraint—Animal, Water, and Wind Power .....	34
4.2	Accumulating Knowledge—Science and Engineering Writings .....	37
4.3	The First Standardization—The Harappan Culture...	39
4.4	Imperial China.....	44
4.5	The Roman Empire.....	52
	Bibliography .....	60
<b>Chapter 5</b>	The Middle Ages in Europe.....	63
5.1	The Rise of the Towns .....	64
5.2	Agricultural Developments.....	66
5.3	Spread of Early Labor-Saving Technology .....	68
5.4	The Role of Medieval Guilds .....	70
5.5	The Putting-Out System .....	76
	Bibliography .....	78
<b>SECTION II The Industrial Revolution— Manufacturing Gets Mechanized</b>		
<b>Chapter 6</b>	Early Modern Europe.....	81
6.1	Manufacturing Technology .....	82
6.2	Working Together—The Emergence of the Manufactory.....	83
	Bibliography .....	86
<b>Chapter 7</b>	Pioneers of a New Age—The Factory System.....	87
7.1	The Arsenal of Venice—The Largest Industrial Site in Europe of Its Time .....	88
7.2	Ironmonger Ambrose Crowley and the Economies of Scale.....	94
7.3	Potter Josiah Wedgwood—The Science of Manufacturing Processes.....	97

7.4	John Lombe's Silk Mill in Derby—Mechanization and Industrial Espionage.....	102
7.5	Sir Richard Arkwright and the Cromford Cotton Mill—Full-Scale Mechanization .....	106
7.6	The Montgolfier Paper Mill—Pioneer in Human Relations.....	110
	Bibliography .....	115
<b>Chapter 8</b>	<b>Fire Is Stronger than Blood and Water—Steam Power...</b>	<b>117</b>
8.1	The Development of the Steam Engine.....	117
8.2	The First Engineering Workshops—Matthew Boulton and the Soho Manufactory.....	122
8.3	Power Goes Mobile—Steam Powered Locomotion ...	127
8.4	Steel—A New Industry Based on Fire and Iron .....	130
8.5	The Invisible Industry—Chemicals .....	133
	Bibliography .....	138
<b>Chapter 9</b>	<b>Interchangeable Parts—The End of Filing in Assembly .....</b>	<b>141</b>
9.1	Honoré Blanc and French Musket Production.....	144
9.2	Block Production at Portsmouth.....	151
9.3	The Unwilling Entrepreneur—Eli Terry's Wooden Clocks.....	159
9.4	Springfield and Harpers Ferry Armories—The American System of Manufacturing.....	161
9.5	What about Eli Whitney? .....	172
	Bibliography .....	174
<b>Chapter 10</b>	<b>Social Conflict.....</b>	<b>177</b>
10.1	Effect on Society.....	178
10.2	Destroy What Destroys You—Luddite Frame Breaking.....	181
10.3	Working Conditions in the Factories .....	184
10.4	Government Actions for the Workers .....	189
	Bibliography .....	191

## SECTION III Modern Times—Mass Production for the Masses

<b>Chapter 11</b>	Technological Advances .....	195
11.1	Infinite Power—Electricity.....	196
11.2	New Manufacturing Technologies Based on Electricity .....	204
11.3	Plastics and Rubber .....	207
11.4	Machine Technology.....	209
11.5	Screwed—Reversible Fasteners.....	213
	Bibliography .....	214
 <b>Chapter 12</b>	 Science Meets Shop Floor .....	 217
12.1	The Beginning of Manufacturing Management .....	217
12.2	Frederick Winslow Taylor—The Father of Scientific Management .....	222
12.3	Taylor’s Legacy .....	233
12.4	Further Progress in Scientific Management .....	235
12.5	The Development of Time Studies—REFA and MTM.....	239
	Bibliography .....	243
 <b>Chapter 13</b>	 The Assembly Line and the Era of the Industrial Empires .....	 245
13.1	The First Assembly Lines—Consumer Products ...	246
13.2	Building an Industrial Empire—Mass Production Needs Mass Selling.....	253
13.3	Sewing Machines, Typewriters, and the Bicycle Craze.....	255
13.4	The Birth of the Automobile .....	259
13.5	The Father of Mass Production—Henry Ford and His Model T .....	263
13.6	The Flaws of Fordism and the Rise of GM.....	275
	Bibliography .....	280
 <b>Chapter 14</b>	 Centrally Planned Economies—War, Communism, and Other Catastrophes.....	 283
14.1	World War I.....	284

14.2	World War II .....	286
14.3	Postwar Economic Miracles.....	291
14.4	The Failed Experiment—Communism .....	293
14.5	Communist Russia—Five-Year Plans for Chaos ....	294
14.6	Communist China—The Great Leap Forward into the Great Famine .....	299
	Bibliography .....	303

<b>Chapter 15</b>	*Click* Let-Me-Do-This-for-You *Clack*—Computers in Manufacturing.....	305
15.1	Continuous Processing Industry.....	306
15.2	Computer-Controlled Machine Tools .....	307
15.3	The Helping Hand—Industrial Robots .....	312
15.4	Computerized Production Planning.....	318
	Bibliography .....	322

<b>Chapter 16</b>	The Toyota Production System and Lean Manufacturing .....	325
16.1	The Founding of Toyota.....	327
16.2	Taiichi Ohno and the Toyota Production System....	332
16.3	The West Wakes Up.....	340
16.4	Lean Manufacturing—The New Religion?.....	342
16.5	Gurus and Snake Oil Salesmen .....	345
16.6	What Else Happened besides Lean?.....	347
	Bibliography .....	351

## SECTION IV The Cutting Edge

<b>Chapter 17</b>	Where Are We Now?.....	357
17.1	Significance of Manufacturing .....	359
17.2	Lessons Learned from History .....	361
17.3	The Big Potential: Decision Making .....	363
17.4	Need for Speed .....	367
17.5	Need for Flexibility.....	369
17.6	Need for Labor Relations.....	372
	Bibliography .....	373

<b>Chapter 18 Things to Come</b> .....	375
18.1 Three-Dimensional Printing.....	375
18.2 Downfall of the Automotive Industry.....	378
18.3 Rise of Robotics.....	382
18.4 The End of Work? .....	385
Bibliography .....	388
 Timelines.....	 391
Index.....	393
About the Author.....	411