

Table of Contents

Summary	6
Table of Mathematical Symbols	8
1 INTRODUCTION	11
1.1 Basic notions of acceptance sampling	11
1.2 Sampling inspection by attributes	13
1.3 Sampling inspection by variables	15
1.4 (P1, P2) sampling plans	16
1.5 AOQL and LTPD plans	18
1.6 Probability distributions used in acceptance sampling	20
1.7 Some tools for testing the normal distribution assumption	25
1.8 Overview of R functions for testing normality	28
2 AOQL VARIABLES PLANS AND COMPARISON WITH THE ATTRIBUTES PLANS	31
2.1 Introduction	31
2.2 AOQL plans for inspection by variables and attributes	33
2.3 Calculation and economical aspects of the AOQL plans for inspection by variables and attributes	38
2.4 Evaluation of efficiency for Lot Tolerance Percent Defective plans	42
2.4.1 Introduction	43
2.4.2 Calculation and economic characteristics of LTPD plans for inspection by variables and attributes	43
2.4.3 Conclusions	47
3 TOOLS FOR COMPUTATION OF AOQL VARIABLES PLANS	49
3.1 A primer on the R language for statistical computing	49
3.2 The R package for computation of AOQL sampling plans	50
3.2.1 AOQL plans with LTPDvar package	52
3.2.2 Functions for computation of sampling plans	55
3.2.3 Note on theoretical background of the computations of plans	71
3.2.4 Performance of the LTPDvar functions for AOQL plans	74
4. FURTHER DEVELOPMENT	79
4.1 Optimization techniques	80
4.1.1 Case study 1: Differential evolution and threshold accepting	81
4.1.2 Case study 2: Local search and threshold accepting	87
Bibliography	93
Index	95