

## Contents

|                                                                                            | Page   |
|--------------------------------------------------------------------------------------------|--------|
| 1.1. Introduction                                                                          | 5      |
| 1.2. The calculation of phase equilibria                                                   | 7      |
| 1.3. Models                                                                                | 7      |
| 1.4. The creation of a consistent thermodynamic database                                   | 10     |
| 1.4.1. First condition of consistency                                                      | 10     |
| 1.4.2. Second condition of consistency                                                     | 11     |
| 1.4.3. Third condition of consistency                                                      | 11     |
| 1.5. The scope of the MP0602 thermodynamic database for high temperature lead-free solders | 12     |
| 1.6. Critical assessment of thermodynamic data                                             | 13     |
| 1.6.1. Testing                                                                             | 14     |
| 1.7. Organisation of the volume                                                            | 15     |
| 1.7.1. Binary systems                                                                      | 15     |
| 1.7.2. Ternary systems                                                                     | 15     |
| 1.7.3. Table of crystallographic structures                                                | 16     |
| 1.8. Concluding remarks                                                                    | 16     |
| 1.9. References                                                                            | 17     |
| 1.10. General references                                                                   | 17     |
| <br>2. Binary systems                                                                      | <br>19 |
| Ag-Ge                                                                                      | 21     |
| Ag-Pb                                                                                      | 23     |
| Ag-Zn                                                                                      | 25     |
| Al-Ga                                                                                      | 27     |
| Al-Ge                                                                                      | 29     |
| Al-Mg                                                                                      | 31     |
| Al-P                                                                                       | 33     |
| Al-Pb                                                                                      | 35     |
| Al-Pd                                                                                      | 37     |
| Al-Sn                                                                                      | 39     |
| Al-Zn                                                                                      | 41     |
| Au-Ga                                                                                      | 43     |
| Au-Ge                                                                                      | 46     |
| Au-Pb                                                                                      | 48     |
| Au-Sb                                                                                      | 50     |
| Au-Si                                                                                      | 52     |
| Au-Sn                                                                                      | 54     |
| Au-Zn                                                                                      | 56     |
| Bi-Cu                                                                                      | 60     |

|       |     |
|-------|-----|
| Bi-Ga | 63  |
| Bi-Ni | 65  |
| Co-Cu | 67  |
| Co-Ni | 69  |
| Co-Pd | 71  |
| Co-Sn | 73  |
| Cu-Ge | 75  |
| Cu-Mg | 78  |
| Cu-P  | 80  |
| Cu-Sn | 82  |
| Ga-Ge | 85  |
| Ga-Mg | 87  |
| Ga-Ni | 89  |
| Ga-P  | 91  |
| Ga-Pb | 93  |
| Ga-Sn | 95  |
| Ga-Ti | 97  |
| Ga-Zn | 100 |
| Ge-Ni | 102 |
| Ge-Pb | 105 |
| Ge-Sb | 107 |
| Ge-Si | 109 |
| Ge-Sn | 111 |
| Ge-Ti | 113 |
| Ge-Zn | 115 |
| Mg-Ni | 117 |
| Mg-Sn | 119 |
| Mg-Zn | 121 |
| Ni-Pb | 123 |
| Ni-Sb | 125 |
| Ni-Sn | 127 |
| P-Sb  | 130 |
| P-Sn  | 132 |
| Sb-Si | 136 |
| Sn-Ti | 138 |

### 3. Ternary systems 141

|          |     |
|----------|-----|
| Ag-Au-Ge | 143 |
| Ag-Cu-Pb | 147 |
| Al-Sn-Zn | 152 |
| Au-Ge-Sb | 157 |
| Au-Ge-Sn | 162 |
| Bi-Cu-Ni | 168 |

---

|    |                                                 |     |
|----|-------------------------------------------------|-----|
|    | Cu-Ni-Sn                                        | 175 |
|    | Cu-Pb-Sn                                        | 185 |
|    | Ni-Sb-Sn                                        | 195 |
| 4. | Appendix – Table of Crystallographic Structures | 205 |