

CONTENTS

ix

PAGE

CHAPTER 5. ANALYSIS OF VARIANCE 71

Additive Properties of the Variance—Sources of Variation—Data with One Criterion of Classification—Experimental Error—Variance between Samples—Null Hypothesis—Analysis of Variance Tables—Sums of Squares—Different Numbers of Observations—Interpretation of Results—Application of *t*-test—Data with Two Criteria of Classification, One being a Subclassification of the Other—Additive Properties—Variance between Groups—Data which may be classified independently with respect to Two Criteria—Sums of Squares—Interpretation of Results—Interaction—Data with Three Criteria of Classification—Further Applications of Analysis of Variance—Different Numbers—General Case: Numbers not Proportional

APPENDICES: 5A. Algebraic Identity for Sums of Squares: Data with One Criterion of Classification—5B. Arithmetical Procedure of Analysis of Variance for Example of § 5.2—5C. Analysis of Variance of Data with One Criterion of Classification: Procedure for General Case—5D. Arithmetical Procedure of Analysis of Variance for Example of § 5.32—5E. Analysis of Variance for Data with Two Criteria of Classification, one being a Subclassification of the Other: Procedure for General Case—5F. Arithmetical Procedure for Analysis of Variance for Example of § 5.41—5G. Sums of Squares for Data with Two-way Classification: Algebraic Treatment—5H. Arithmetical Procedure for Analysis of Variance for Example of § 5.5—5K. Test for Homogeneity of Variances (Bartlett Test)—5L. Estimation of Missing Values

CHAPTER 6. REGRESSION AND CORRELATION 118

Regression—One Variate subject to Error—Relation between Two Variates—Types of Regression—Significance of Regression—Errors arising in the Use of the Regression Equation for Prediction Purposes—Rubber-testing Regression—Penicillin Regression—Regression: General—Correlation—Correlation Coefficient—Relation between Correlation Coefficient and Regression Coefficient—Significance of Correlation Coefficient—Covariance—Correlation *v.* Regression—Non-linear Regression—Multiple Regression and Correlation—Partial Regression Coefficients—Significance of Partial Regression Coefficients—Multiple Regression for several Independent Variates

APPENDICES: 6A. To fit a Straight Line to Data by the Method of Least Squares—6B. Calculation of Regression for Penicillin Example—6C. Standard Error of Regression Coefficient—6D. Accuracy of Predictions using Regression Equations—6E. Calculation of Correlation Coefficient—6F. Calculation of Correlation Coefficient from Grouped Data—6G. Fitting Curvilinear Regression for Equally Spaced Ordinates—6H. Application of Least Squares Method to Multiple Regression with Two Independent Variates—6K. Significance of Partial Regression Coefficients

CONTENTS

	PAGE
LIST OF CONTRIBUTORS	iv
FOREWORD by LORD MCGOWAN, K.B.E., D.C.L., LL.D.	v
AUTHORS' PREFACE	vi
FIGURES	xi
CHAPTER 1. INTRODUCTION	1
Object of Handbook—Statistical Methods—Types of Problem to which Statistical Methods may be Applied—Terminology	
CHAPTER 2. FREQUENCY DISTRIBUTIONS	6
Frequency Tables—Grouping—Graphical Representation—Histogram— Frequency Polygon—Frequency Curves—Cumulative Frequency Curve or Ogive—Universe—Normal Distribution—Standard Measure—Tests for Normality—Probability Paper—Transformation of the Variable— Samples and Sampling Fluctuations	
CHAPTER 3. AVERAGES AND MEASURES OF DISPERSION	24
Averages—Arithmetic Mean—Geometric Mean—Harmonic Mean— Median—Mode—Measures of Dispersion—Variance—Degrees of Free- dom—Standard Deviation—Coefficient of Variation—Computations— Range—Mean Deviation—Measures of Skewness—Reliability of Mean Variance and Standard Deviation—Standard Error—Standard Error of Functions of Variates	
APPENDICES: 3A. Computation of Arithmetic Mean—3B. Computation of Variance: Ungrouped Data—3C. Computation of Variance: Grouped Data—3D. Computation of Variance from a Number of Samples—3E. Standard Error of a Function of Variables—3F. Proof of Equation (3.75)—3G. Proof of Equation (3.42)—3H. Degrees of Freedom—3K. Presentation of Data	
CHAPTER 4. TESTS OF SIGNIFICANCE	51
Procedure: Null Hypothesis—Significance Levels—Degrees of Freedom —Significance of a Mean—The <i>t</i> -test—Process of Pairing—The <i>F</i> -test— Comparison of Several Variances	
APPENDICES: 4A. The <i>t</i> -test: Universe Mean known exactly—4B. The <i>t</i> -test: Difference Method—4C. Comparison of Sample Means— 4D. The <i>F</i> -test—4E. The <i>t</i> -test regarded as Analysis of Variance— 4F. Single- and Double-tailed Tests	

FIGURES

FIGURE	PAGE
2.1 Frequency Curve	6
2.2 Histogram	10
2.3 Cumulative Frequency Curve (Ogive)	13
2.4 Curve of Normal Distribution	15
2.5 Normal Distribution—Graph of Equation (2.3)	16
2.6 Curve of Normal Distribution—Standardised Deviate	17
2.7 Curve of Normal Distribution—Standardised Deviate (Double Tail)	18
3.1 Symmetrical and Non-symmetrical Frequency Curves	33
6.1 Correlation Diagram: Abrasion Loss <i>v.</i> Hardness	118
6.2 Penicillin: Relation between Circle Diameter and Concentration	122
6.3 Regression Lines	124
6.4 Standard Deviation of Predictions of Abrasion Loss from Hardness	132
6.5 Diagram for Illustrating Method of Least Squares	147
6.6 Schopper Riegler Freeness Test of Paper Pulp during Beating	162
9.1 Lack of Control of Averages	220
9.2 Lack of Control of Ranges	221
9.3 Lack of Control of Averages and Ranges	222
9.4 Control Charts: Initial Set	232
9.5 Control Charts: Initial Set, Samples 5 and 13 omitted	233
9.6 Control Charts: Hardening Rate	235
Nomogram	285